


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Stone chips in windscreen.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Poor
Carpets:	Good
Panels:	Average
Dashboard:	Good

Vehicle drove ok.

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Cambelt	
Evidence of Cam Belt Replacement		☒ Yes ☐ No	123,917 Kms
Inspected by:	Aaron Johnson		
Published by:	Aaron Johnson		
Inspection Date:	21 Aug 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood
this condition guide: