

Report ID:	28,416,347	Version:	2
Created:	21 Aug 2026		


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2013
Rego No.:	KLK327	Rego Expiry:	11 Aug 2026
WoF Expiry:	07 Apr 2027	Odometer:	215,539 Kms
Good No.:	28416347	VIN:	7AT0H60FX17174864
Next Service:	can't read	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear bumper damage, r brake light cracked, rear bumper torn, interior tail gate rust and dent, number plate not working, both front tyre side wall cracked, r rear tyre cracked, engine oil leak, both front wheel play.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Odo: 214539 kms

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Both front seat belt frayed, windscreen cracked cva out cva, front wiper blade worn, L wing mirror broken not folding, passenger seat have hole,

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Marlon Espena
Published by:	Marlon Espena
Inspection Date:	21 Aug 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	3 mm		
Right front	3 mm		
Left rear	3 mm		
Right rear	3 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera		✓	