

Report ID:	28,421,417	Version:	2
Created:	26 Aug 2026		


Make:	Volkswagen	Model:	T6
Body Style:	Van	Year:	2018
Rego No.:	LKP937	Rego Expiry:	28 Feb 2027
WoF Expiry:	20 Oct 2026	Odometer:	101,834 Kms
Good No.:	28421417	VIN:	WV1ZZZ7HZJH138545
Next Service:	100,000 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both taillights cracked, high stop light cracked, rear wiper blade worn, left rear reflector cracked, rear wiper blade plastic cover missing, left tail gate strut missing, engine oil leak, left sliding door refit.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Service due

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

General Comments

Driver seat belt frayed, windscreen cracked major, both wing mirror plastic cover not working, front wiper blade worn, interior cargo area trim boards damage.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	☐ Yes ☒ No Kms
Inspected by:	Marlon Espena
Published by:	Henry Manders
Inspection Date:	25 Aug 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7.0 mm
Right front			7.0 mm
Left rear			9.0 mm
Right rear			9.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____