


Make:	Mazda	Model:	CX-9
Body Style:	SUV	Year:	2021
Rego No.:	NRN733	Rego Expiry:	08 Feb 2027
WoF Expiry:	27 Aug 2027	Odometer:	82,220 Kms
Good No.:	28428740	VIN:	JM0TC4WLA00503394
Next Service:	88,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

RH taillight cracked.
RR wheel flare damaged.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Caleb Spicer Lee		
Published by:	Caleb Spicer Lee		
Inspection Date:	28 Aug 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE