

Report ID:	28,431,149	Version:	2
Created:	06 Oct 2026		


Make:	Volkswagen	Model:	T6
Body Style:	Van	Year:	2018
Rego No.:	LKN823	Rego Expiry:	24 Nov 2026
WoF Expiry:	13 Jul 2027	Odometer:	156,501 Kms
Good No.:	28431149	VIN:	WV1ZZZ7HZJH130160
Next Service:	157440	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Roof rack key missing,windscreen stone chip out cva,FR door noisy when opening,FR seat belt frayed,FR door seal torn,R wing mirror unsecure ,L taillight crack,FL mud flap unsecure,RL tyre sidewall crack,spare tools and jack missing, left front mudflap loose,

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

A/C compressor oil leak,transmission minor oil leak,

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Right Front Door Check Strap Faulty, Cargo Area Interior Trim cracked

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	☒ Yes ☐ No 96,450 Kms
Inspected by:	Curshey Accad
Published by:	Darryl Kereti
Inspection Date:	06 Sep 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6.0 mm
Right front			6.0 mm
Left rear			6.0 mm
Right rear			6.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		