

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Domestic wall charger and fast charger available
Windscreen stone chip cracked
FB grille cracked

Rwd

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Unknown		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Vasanthakumar Mayilswamy		
Published by:	Vasanthakumar Mayilswamy		
Inspection Date:	31 Aug 2026		

NAME _____

SIGNATURE

Engine			
Oil level			✓
Smoke & fumes			✓
Engine performance			✓
Noise			✓
Coolant condition	✓		
Cooling performance			✓
Radiator / Hoses (visual)			✓
Transmission			
Operation			✓
Noise			✓
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	6 mm		
Right front	6 mm		
Left rear	5 mm		
Right rear	5 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		