


Make:	Toyota	Model:	Corolla
Body Style:	Hatchback	Year:	2020
Rego No.:	MZF320	Rego Expiry:	27 Oct 2026
WoF Expiry:	24 Jul 2027	Odometer:	118,810 Kms
Good No.:	28439961	VIN:	JTNK93BE403022280
Next Service:	124000	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
-----------------------------------	-----

Front wheel drive

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:		Jaykib Collins	
Published by:		Jaykib Collins	
Inspection Date:		04 Sep 2026	

I have read and understood
this condition guide:

NAME _____

SIGNATURE