

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,442,869  | Version: | 2 |
| Created:   | 09 Sep 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mazda       | Model:           | Bt-50             |
| Body Style:   | Utility     | Year:            | 2019              |
| Rego No.:     | LWN551      | Rego Expiry:     | 26 Jun 2027       |
| WoF Expiry:   | 23 Sep 2027 | Odometer:        | 245,165 Kms       |
| Good No.:     | 28442869    | VIN:             | MM0UR0YG100899253 |
| Next Service: | 246,000kms  | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Right front door seal is torn. Canopy key is missing.

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

|            |                                   |
|------------|-----------------------------------|
| Seats:     | Hole in right front base pad.     |
| Carpets:   | Good                              |
| Panels:    | Handles paint fading.             |
| Dashboard: | AT shift boot refitting required. |

### General Comments

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Yuki Itohara                 |                             |     |
| Published by:                     | Melissa Wilson               |                             |     |
| Inspection Date:                  | 08 Sep 2026                  |                             |     |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

**SIGNATURE**

|                                              | OK  | Requires<br>Attention | N/A    |
|----------------------------------------------|-----|-----------------------|--------|
| Engine                                       |     |                       |        |
| Oil level                                    | ✓   |                       |        |
| Smoke & fumes                                | ✓   |                       |        |
| Engine performance                           | ✓   |                       |        |
| Noise                                        | ✓   |                       |        |
| Coolant condition                            | ✓   |                       |        |
| Cooling performance                          | ✓   |                       |        |
| Radiator / Hoses (visual)                    | ✓   |                       |        |
| Transmission                                 |     |                       |        |
| Operation                                    | ✓   |                       |        |
| Noise                                        | ✓   |                       |        |
| Clutch                                       |     |                       | ✓      |
| CV joints                                    | ✓   |                       |        |
| Wheel bearings                               | ✓   |                       |        |
| Brakes                                       |     |                       |        |
| Performance                                  | ✓   |                       |        |
| Hand brake                                   | ✓   |                       |        |
| Tyres (lowest observed tread depth of tyres) |     |                       |        |
| Left front                                   |     |                       | 9.0 mm |
| Right front                                  |     |                       | 9.0 mm |
| Left rear                                    |     |                       | 8.0 mm |
| Right rear                                   |     |                       | 8.0 mm |
| Spare                                        | Yes |                       |        |
| Suspension                                   |     |                       |        |
| Suspension performance                       | ✓   |                       |        |
| Steering performance                         | ✓   |                       |        |
| Shock absorbers                              | ✓   |                       |        |
| Air Conditioning / Heater                    |     |                       |        |
| Operation                                    | ✓   |                       |        |
| Electrical / Accessories                     |     |                       |        |
| Head lights                                  | ✓   |                       |        |
| Tail lights                                  | ✓   |                       |        |
| Indicators                                   | ✓   |                       |        |
| Dashboard warning lights                     | ✓   |                       |        |
| Wipers (front & rear)                        | ✓   |                       |        |
| Window winder FL                             | ✓   |                       |        |
| Window winder FR                             | ✓   |                       |        |
| Window winder RL                             | ✓   |                       |        |
| Window winder RR                             | ✓   |                       |        |
| Rear view mirrors                            | ✓   |                       |        |
| Radio (basic test only)                      | ✓   |                       |        |
| CD (basic test only)                         | ✓   |                       |        |
| Number of keys                               | 3   |                       |        |
| Central locking                              | ✓   |                       |        |
| Remote locking                               | ✓   |                       |        |
| Sat. nav. (basic test only)                  |     |                       | ✓      |
| Reversing camera                             | ✓   |                       |        |