


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2020
Rego No.:	MRS438	Rego Expiry:	12 Feb 2027
WoF Expiry:	16 Oct 2027	Odometer:	139,025 Kms
Good No.:	28453581	VIN:	MR0KA3CD301238667
Next Service:	148,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



All 4 Wheels require centre caps to be refit, caps in the cab

Underbody Surface Rust
Surface Rust Developing on lower radiator support

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Jaden Jenkins		
Published by:	Kenneth Mak		
Inspection Date:	22 Sep 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE