


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2021
Rego No.:	NJT963	Rego Expiry:	22 Mar 2027
WoF Expiry:	23 May 2027	Odometer:	134,608 Kms
Good No.:	28456996	VIN:	MR0JA3DD600347804
Next Service:	144,500km	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
-----------------------------------	-----

2Wheel drive.

Seats:	RF seat torn.
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Rajesh Mayan		
Published by:	Andrew Sullivan		
Inspection Date:	14 Sep 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE