


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2022
Rego No.:	PLR251	Rego Expiry:	01 Mar 2027
WoF Expiry:	09 Sep 2027	Odometer:	94,620 Kms
Good No.:	28459939	VIN:	MR0CX3CD300121034
Next Service:	78,858	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Wet
-----------------------------------	-----

Seepage from front shock absorbers

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:	Samuel Weir		
Published by:	Samuel Weir		
Inspection Date:	11 Sep 2026		

SIGNATURE