

Report ID:	28,471,351	Version:	2
Created:	22 Sep 2026		


Make:	Subaru	Model:	Impreza
Body Style:	Hatchback	Year:	2008
Rego No.:	NQH874	Rego Expiry:	18 Aug 2026
WoF Expiry:	15 Jul 2027	Odometer:	182,023 Kms
Good No.:	28471351	VIN:	7AT0GF09X21006025
Next Service:	185,000kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper loose.
L/F weather shield broken.
Right sill skirt pin dented.
Front guard liners damaged & under trays missing.

Conditions During Body Inspection	Wet
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Oil seepage from rear differential.
Modified suspension & exhaust.

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Console lid damaged. aftermarket gear knob.
Dashboard:	Vents damaged. steering column shroud loose.

General Comments

AWD turbo hatch.
Note: Adjustable rear suspension not certified (comes with the original rear suspension)

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	☐ Yes ☒ No Kms
Inspected by:	Daryll Timms
Published by:	Shane Charlton
Inspection Date:	16 Sep 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4.0 mm
Right front			4.0 mm
Left rear			3.0 mm
Right rear			4.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____