


Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2021
Rego No.:	NLU216	Rego Expiry:	17 May 2027
WoF Expiry:	25 May 2027	Odometer:	156,532 Kms
Good No.:	28494129	VIN:	MNTCBAD23A0000534
Next Service:	161000	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Body Inspection Comments

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Jaykib Collins		
Published by:	Jaykib Collins		
Inspection Date:	01 Oct 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE