


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2007
Rego No.:	KPJ348	Rego Expiry:	16 May 2027
WoF Expiry:	21 Apr 2027	Odometer:	184,129 Kms
Good No.:	28509004	VIN:	7AT0H60FX16050238
Next Service:	191,575kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Some rusty spots on roof.
Left tail light cracked.
Rear wiper removed, replaced with a reverse camera.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Daryll Timms		
Published by:	Leon Sun		
Inspection Date:	05 Oct 2026		

NAME _____

SIGNATURE