

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,510,861  | Version: | 1 |
| Created:   | 06 Oct 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Ford        | Model:           | Transit           |
| Body Style:   | Van         | Year:            | 2013              |
| Rego No.:     | GUB607      | Rego Expiry:     | 10 Jan 2027       |
| WoF Expiry:   | 22 May 2027 | Odometer:        | 202,234 Kms       |
| Good No.:     | 28510861    | VIN:             | WF0YXXTTGYCT12704 |
| Next Service: | 214,000 Kms | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

RF sill/wheel arch worn. RF door seal torn.  
Rear door ford badge missing. Aerial stalk missing.  
GPS knob on roof and additional aerial on LF guard.  
RF guard/mirror moulding loose.

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

Both front inner guard liners missing.  
Minor engine oil leak.

## Interior Comments

Seats: Good  
Carpets: Good  
Panels: Average, cargo area panels damaged.  
Dashboard: Good, steering wheel wearing.

## General Comments

Aftermarket 1000W power inverter fitted in cargo area.  
Aftermarket reverse camera.  
Front rotating beacon light not working.

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Troy Smith                   |                             |     |
| Published by:                     | Troy Smith                   |                             |     |
| Inspection Date:                  | 06 Oct 2026                  |                             |     |

OK Requires Attention N/A

## Engine

|                           |   |  |  |
|---------------------------|---|--|--|
| Oil level                 | ✓ |  |  |
| Smoke & fumes             | ✓ |  |  |
| Engine performance        | ✓ |  |  |
| Noise                     | ✓ |  |  |
| Coolant condition         | ✓ |  |  |
| Cooling performance       | ✓ |  |  |
| Radiator / Hoses (visual) | ✓ |  |  |

## Transmission

|                |   |  |  |
|----------------|---|--|--|
| Operation      | ✓ |  |  |
| Noise          | ✓ |  |  |
| Clutch         | ✓ |  |  |
| CV joints      | ✓ |  |  |
| Wheel bearings | ✓ |  |  |

## Brakes

|             |   |  |  |
|-------------|---|--|--|
| Performance | ✓ |  |  |
| Hand brake  | ✓ |  |  |

## Tyres (lowest observed tread depth of tyres)

|             |        |
|-------------|--------|
| Left front  | 7 mm   |
| Right front | 7.5 mm |
| Left rear   | 6.5 mm |
| Right rear  | 6 mm   |
| Spare       | Yes    |

## Suspension

|                        |   |  |  |
|------------------------|---|--|--|
| Suspension performance | ✓ |  |  |
| Steering performance   | ✓ |  |  |
| Shock absorbers        | ✓ |  |  |

## Air Conditioning / Heater

|           |   |  |  |
|-----------|---|--|--|
| Operation | ✓ |  |  |
|-----------|---|--|--|

## Electrical / Accessories

|                             |   |  |   |
|-----------------------------|---|--|---|
| Head lights                 | ✓ |  |   |
| Tail lights                 | ✓ |  |   |
| Indicators                  | ✓ |  |   |
| Dashboard warning lights    | ✓ |  |   |
| Wipers (front & rear)       | ✓ |  |   |
| Window winder FL            | ✓ |  |   |
| Window winder FR            | ✓ |  |   |
| Window winder RL            |   |  | ✓ |
| Window winder RR            |   |  | ✓ |
| Rear view mirrors           | ✓ |  |   |
| Radio (basic test only)     | ✓ |  |   |
| CD (basic test only)        | ✓ |  |   |
| Number of keys              | 3 |  |   |
| Central locking             | ✓ |  |   |
| Remote locking              | ✓ |  |   |
| Sat. nav. (basic test only) |   |  | ✓ |
| Reversing camera            | ✓ |  |   |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_